MOUNTING PROCEDURE

KIT WINDSHIELD KTM SUPERDUKE 1290

KTM1300

KIT

X1. PLEXIGLASS X4. SPECIFIC BRACKET

X2. THICKNESS

X2. NUT Ø 6
X4. NUT Ø 5 AUTOLOCKED
X4. SCREW "ROUND HEAD" 5X12
X2. SCREW "ROUND HEAD" 5X50
X2. SCREW "ROUND HEAD" 6X14

X2. WASHER Ø 6 LARGE X4. WASHER Ø 5 LARGE


X4. TEFLON WASHER Ø 5

X4. RUBBER WASHER

WWW.BARRACUDAMOTO.COM

FIXING PROCEDURE:

- REMOVE THE ORIGINAL SCREWS HIGHLIGHTENED FROM THE FRONT COVER;
- APPROACH THE TWO SPECIFIC BRACKETS (A-B) AND THE RELATIVE THICKNESS LIKE THE SCHEME;
- FIND THE RIGHT POSITION OF WINDSHIELD ON THE ALREADY FIXED BRACKETS AND LOCK ALL THE SCREWS;



NOTE: DON'T LOCK TOO MUCH TO AVOID PLEXIGLASS BROKEN.